

Division of Oil, Gas, & Mining  
Mining Report

05/25/93

MINE ID: S0370080

MINE NAME: LASAL MILL

OPERATOR: SAGUARRO MINING  
CONTACT: LARRY HILL  
ADDRESS: LASAL JUNCTION  
LASAL JUNCTION UT 84530  
PHONE: (801)686-2365

Surface Owner: FEE  
Mineral Owner: FEE

BLM #:  
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
						0	0.0	0.0

Permit Status: NAP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): PRO

Acreage: 0

Minerals Mined

DATE  
RECEIVED

TENTATIVE APPROVAL  
DATE

FINAL APPROVAL  
DATE

LAST INSPECTED

/ /

/ /

/ /

05/05/93

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR:

	YTD	Total					
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/

COMMENTS:

THIS IS AN UNPERMITTED SITE. THE SITE WAS PERMITTED EARLIER BY MR. PAUL SCOFIELD. MR. SCOFIELD RECLAIMED THE SITE SHORTLY AFTER INITIATING OPERATION TWO YEARS PREVIOUS (1991). NEW OWNERS HAVE TAKEN OVER THE SITE & INITIATED A NEW GOLD MILLING OPERATION. SMO WAS GIVEN TO THE NEW OPERATOR. JOHN STEVENSON IS INVOLVED IN DEVELOPING THE SITE.